

## **Airworthiness Directives**

## AMP Reference: IAL/330/T Revision 00 Initial

## Airworthiness Directive Compliance

The Airworthiness Directives in accordance with the CAME procedure (fill in your reference here) are reviewed on a bi-weekly basis for MSN 389.

To avoid continual AMP revision update, the Airworthiness Directives are managed on form: IALTA\_AD\_Tracking Revision 00 Revision date 5 Jan 2021

>><	IAL					Document No. IALTA_AD_Trackin Document Revision 0 Document Date 30 Jan 202
		Airworth	iness Directive Cont	trol Docume	nt	
АС Туре	REG	MSN	TSN	CSN	C	Current Date
A330-343	EI-MYT	389	50278	17899		10.FEB.2022
<b>Revision Code</b>	Authority	AD Numner	Document Reference	AMP Threshold	AMP Interval	Comment
81	EASA	2015-0120R1	SB A330-57-3096 Revision 0	5 09-Aug-15	300 FC or 900 FH	Initial inspoection 3 JUN 200 CYC 12654 on now superseeded AD.